Type L # Hits Search Text	L # Hits Search Text	Hits Search Text	Search Text		DBs	Time Stamp	Comment	Error Definition	Er ro rs
BRS L1 510 (girder with deck) and connect\$	510 (girder with and connect\$	(girder with and connect\$			USPAT; US-PGPUB; 2004/10/14 EPO; JPO; DERWENT; IBM_TDB 11:27	2004/10/14 11:27			0
(girder with deck) and connect\$ and BRS L2 25 fasten\$ and (precast prefabricated) with deck)	25		(girder with deck) and connect\$ and fasten\$ and ((precontect) prefabricated) withdeck)	,	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 11:36			0
BRS L3 7 "4809421" "4710994" "4809421" "4831675" "5025522" "5617599").PN.	("3253289" 4709435" "4809421" 4831675" "5617599")	("3253289" "4709435" "4809421" "4831675" "5617599")	("3253289" "4709435" "471099 "4809421" "4831675" "502552 "5617599").PN.	14"	USPAT	2004/10/14 11:35			0
BRS L4 4 5802652.URPN.	4		5802652.URPN.		USPAT	2004/10/14 11:35			0
BRS L5 10 hwang.in. and girder	10		hwang.in. and girde		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 11:36			0
BRS L6 1589 ls. 404/70.ccls. 248/188.2.ccls.	1589		14/73,73.1,77.1,78. ls. 404/70.ccls. 248/188.2.ccls.		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/14 12:02			0
BRS L7 74 248/188.2.ccls. and deck and girder	74		(14/73,73.1,77.1,78 cls. 404/70.ccls. 248/188.2.ccls.) an deck and girder		USPAT; US-PGPUB; 2004/10/14 EPO; JPO; DERWENT; IBM_TDB 12:02	2004/10/14 12:02			0